



894 Faulstich Ct.
San Jose, CA 95112
Ph: 408-573-2700
Fx: 408-573-2708
www.CXRLarus.com

February 5, 2009

Dear Valued Customer:

CXR Larus had previously announced on January 1, 2005, the manufacturing discontinuance of the STS5400 Series Timing System and all of its attendant cards and modules.

This letter is to inform all of our valued customers that effective January 1, 2010; CXR Larus cease all support or repair the STS5400 Series Timing Products in any capacity. We will take no orders for repair or replacement of parts, components, refurbishment of new cards or shelves as of this date.

CXR Larus will continue to support any orders for repair, spares or replacement cards on the STS5400 Systems for the balance of 2009. All charges during the final service period will be quoted to the customer at the time of request for repair or replacement. Replacement of cards whether new or used will be made on an as available basis and there will be no guarantee that replacement cards will be available for the balance of 2009. No orders will be taken for complete system builds during the balance of 2009.

We look forward to a continuing relationship with each of our loyal customers and supporting your timing and synchronization, transmission and test and measurement needs in the future with our exciting new products. CXR Larus' mission and mandate is provide ever increasing levels of satisfaction to our customers by providing quality products and services, and adding value to our customer's business. Through a commitment to excellence in our products, service and delivery we will continue to meet and exceed your expectations.

Please visit our new website, www.cxrlarus.com, to see what is happening at our company and communications products CXR/Larus has to help you in your business.

Sincerely,

A handwritten signature in black ink, appearing to read 'L. Taillie', with a horizontal line extending to the right.

Lawrence Taillie
President
CXR Larus Corporation